



PORTLAND HARBOUR AUTHORITY LIMITED



Local Notice to Mariners

No 02/2019(T)

NEW SPECIAL MARK BUOY

A Special Mark has been established in position 50°35.11N 002°27.75W

This buoy is marking the end of the old pier remains, an obstruction, as annotated on Chart 2268.



Mariners are requested to navigate with caution when passing inside of this buoy.

This notice is issued under the powers vested by the Portland Harbour Revision Order 1997.

Captain M Shipley
Harbourmaster & Marine Manager
14th February 2019

Owners, Agents, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the Masters or persons in charge of their vessels or craft.