



PORTLAND HARBOUR AUTHORITY LIMITED



Local Notice to Mariners

No 11/2022

INTAKE STRUCTURE SPECIAL MARKS IN NEWTONS COVE

Notice is hereby given that the Intake Structure Special Mark Buoy in approximate position $50^{\circ}36'.220\text{N } 002^{\circ}27.000\text{W}$ has been replaced with two unlit Special Mark Posts, each post marking an intake structure. Chart 2268 will be updated to reflect these changes.



LNTM No 35/2021(T) is hereby revoked

This notice is issued under the powers vested by the Portland Harbour Revision Order 1997.

Captain M Shipley
General Manager (Marine)
25th March 2022

Owners, Agents, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the Masters or persons in charge of their vessels or craft.